

Method for automated surface monitoring and surface correction

Abstract

5

An automated method for surface monitoring and surface correction of sheet-like materials, for example of leather, especially a method for classifying surfaces of sheet-like materials, comprises the following steps:

10

(a) preparation of a material,

(b) optoelectronic recording of the surface of the material,

15 (c) determination of the number of defects,

(d) determination of the volume of defects,

and subsequent automatic classification of the sheet-like
20 materials according to number and volume of defects.

25

30

35

40

45